


1/9



Resistance change with varying x in the system $\text{Ni}_x\text{Co}_{1-x}\text{O}_y$

Fig. 1

2/9




Fig. 2

3/9




Fig. 3

4/9

Sensitivity of NiCo_2O_4 to CO concentrations 500 - 1000400ppm




Fig. 4

5/9




Fig. 5

Recovery of NiCo_2O_4 resistance following exposure to high CO concentrations

6/9




Fig. 6


Recovery of NiCo_2O_4 resistance following exposure to CO concentrations 35 - 400 ppm

Fig. 7

Recovery of NiCO_2O_4 resistance following exposure to CO concentrations 500 - 1000 ppm

8/9




Fig. 8

9/9




Fig. 9